

Cat 6 RJ45 Plug Termination Instructions



1 Ring cut the jacket.




2 Pull off the sheath...




3 and remove.



4 Cut off the rip cord if present.




5 Cut and remove the central sparator.




6 Arrange the wires in to the required sequence


Cat 6 RJ45 Plug Termination Instructions




7 Cut the wires at an angle.



8 Push the wires in to the appropriate holes in the plug insert.




9 Cut the wires flush with the insert.



10 Push the insert in to the plug body....



11 making sure that it sits tightly at the front of the plug.



12 Before crimping check that all wires are in the correct position and pushed fully to the front of the plug.


Cat 6 RJ45 Plug Termination Instructions



13 Insert the plug into the crimp tool...



14 and terminate the plug.



15 Finished.